

Gutters cleaned out and stainless steel spike system installed to stop Pigeons perching and fouling the front of the building.